

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 27-7-2023

Geophysical Borehole Logging Report

As advised by Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Dusaha,
Block Balrampur, District Balrampur, U.P.

Name of Village : Dusaha (82⁰09'53.8"E, 27⁰26'29.1"N)

Block : Balrampur

District : Balrampur

Date : 27-7-2023

Depth logged : 169.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	10	4	Clay with kankar
2	10	42	32	fine to medium sand
3	42	56	14	Clay with kankar
6	56	84	28	fine sand
7	84	87	3	Clay with kankar
8	87	90	3	fine sand
9	90	94	4	Clay with kankar
10	94	98	4	fine sand
11	98	102	4	Clay with kankar
12	102	120	18	fine sand
13	120	131	11	Clay with kankar
14	131	138	7	fine sand
15	138	146	8	Clay with kankar
16	146	150	4	fine sand
17	150	152	2	Clay with kankar
18	152	168	16	fine sand

For First Best Solution

Authorized Signatory
For First Best Solution

Alray
Proprietor