FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:20-12-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Balsinghpur, Block Balha, District Baheraich, U.P.

Name of Village: Balsinghpur (27⁰56'48.5"N,81⁰22'03"E)

Block - Balha

District: Baheraich

: 20-12-2023

Logger use

Depth logged: 302.0 mbgl : Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	43	37	Fine Sand
2	43	47	4	Clay and kankar
3	47	98	51	Fine to medium Sand
4	98	108	10	Clay and kankar
5	108	112	4	Fine sand
6	112	119	7	Clay and kankar
7	119	123	4	Fine sand
8	123	127	4	Clay and kankar
9	127	139	12	Fine sand
10	139	150	11	Sandy Clay and kanka
11	150	162	. 12	Fine sand
12	162	166	4	Clay and kankar
13	166	196	30	Fine sand
14	196	222	26	Clay and kankar
15	222	251	29	Fine sand
16	251	262	11	Clay and kankar
17	262	280	18	Fine sand
18	280	282	2	Clay and kankar
19	282	293	11	Fine sand
20	293	296	3	sandy clay
21	296	302	6	Fine sand

For First Best Solution Authorized Signatory

Satvinder Singh Govt. Contractor Setvinder Singh

For First Best Solution

Proprietor