

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005
Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:30-9-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Madariya, Block Mahipurva, District Bahraich, U.P.

Name of Village : Madariya (81° 32'45.8"E,28°01'12.2"N)

Block – Mahipurva

District: Bahraich

Date : 30-9-2023

Depth logged : 300.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	22	16	Medium to fine sand
2	22	36	14	Clay with kankar
3	36	46	10	Medium to fine sand
4	46	60	14	Clay with kankar
5	60	62	2	fine sand
6	62	66	4	Clay with kankar
7	66	90	24	Medium to fine sand
8	90	94	4	Clay with kankar
9	94	106	12	Medium to fine sand
10	106	128	22	Clay with kankar
11	128	150	22	Medium to fine sand
12	150	172	22	Clay with kankar
13	172	217	45	Medium to fine sand
14	217	222	5	Clay with kankar
15	222	246	24	Medium to fine sand
16	246	274	28	Clay with kankar
17	274	300	26	fine sand

For First Best Solution

Authorized Signatory
For First Best Solution

Niraj
Proprietor