

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:2-11-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Raja Bir Pur Zone 2, Block Hariharpur Rani, District Shravasti, U.P.

Name of Village : Raja Bir Pur Zone 2 (81 48'39.6"E27 41'40.3"N)

Block – Hariharpur Rani

District: Shravasti

Date : 2-11-2023

Depth logged : 164.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	To			
1	6	23	17	fine sand	Good
2	23	45	22	Clay with kankar	
3	45	81	36	fine to medium sand	Good
4	81	87	6	Clay with kankar	
5	87	91	4	fine sand	Good
6	91	95	4	Clay with kankar	
9	95	101	6	fine sand	Good
10	101	110	9	Clay with kankar	
11	110	115	5	fine sand	Good
12	115	125	10	Clay with kankar	
13	125	143	18	fine sand	Good
14	143	155	12	Clay with kankar	
15	155	164	9	fine sand	Good

For First Best Solution

Authorized Signatory
For First Best Solution

Niraj
Proprietor