

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date: 29-7-2023

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Kakrdari, Block Harihar pur Rani, District Shravasti, U.P.

Name of Village : Kakrdari, ( 81.813° E, 27.901° N)

Block – Harihar pur Rani

District: Shravasti

Date : 29-7-2023

Depth logged : 169.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	12	6	fine sand
2	12	26	14	Clay with kankar
3	26	34	8	fine sand
4	34	38	4	Clay with kanar
5	38	42	4	fine sand
6	42	58	16	Clay with kankar
7	58	69	11	fine sand
8	69	74	5	Clay with kankar
9	74	86	12	medium to fine sand
10	86	106	20	Clay with kankar
11	106	113	7	medium to fine sand
12	113	118	5	Clay with kankar
13	118	133	15	medium to fine sand
14	133	140	7	Clay with kankar
15	140	144	4	fine sand
16	144	158	14	Clay with kankar
17	158	163	5	fine sand
18	163	169	6	Clay with kankar

For First Best Solution  
Authorized Signatory

For First Best Solution

*Atiyaj*

Proprietor

*Atiyaj*