

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 10-6-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Buther, Block Sirsiya, District Shravasti, U.P.

Name of Village : Buther

Block – Sirsiya

District: Shravasti

Date : 10-6-2024

Depth logged : 165.0 m.bgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	14	8	fine sand
2	14	17	3	Clay with kankar
3	17	22	5	fine sand
4	22	35	13	Sandy Clay
5	35	40	5	fine sand
6	40	42	2	Clay with kankar
7	42	44	2	fine sand
8	44	55	11	Clay with kankar
9	55	62	7	fine sand
10	62	75	13	Clay with kankar
11	75	81	6	fine sand
12	81	91	10	Clay with kankar
13	91	94	3	fine sand
14	94	110	16	Clay with kankar
15	110	118	8	fine sand
16	118	121	3	Clay with kankar
17	121	129	8	fine sand
18	129	137	8	Clay with kankar
19	137	143	6	fine sand

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
20	143	146	3	Clay with kankar
21	146	149	3	fine sand
22	149	165	16	Clay with kankar

For First Best Solution

Authorized Signatory
For First Best Solution

Proprietor