

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:26-10-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Dhandhara, Block Gesari, District Balrampur, U.P.

Name of Village :Dhandhara

Block –Gesari

District: Balrampur

Date : 26-10-2023


Depth logged : 279.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	To			
1	6	25	19	fine sand	Good
2	25	30	5	Clay with kankar	
3	30	40	10	fine sand	Good
4	40	60	20	Clay with kankar	
5	60	84	24	fine sand	Good
6	84	90	6	Clay with kankar	
9	90	100	10	fine sand	Good
10	100	125	25	Clay with kankar	
11	125	138	13	fine sand	Good
12	138	145	7	Clay with kankar	
13	145	156	11	fine sand	Good
14	156	163	7	Clay with kankar	
15	163	167	4	fine sand	Good
16	167	175	8	Clay with kankar	
17	175	225	50	fine sand	Good
18	225	260	35	Clay with kankar	
19	260	279	19	fine sand	Good

First Best Solution

Authorized Signatory
For First Best Solution

Proprietor