

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:18-10-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Titihirira, Block Sirsiya, District Shrawasti, U.P.

Name of Village : Titihirira

Block – Sirsiya

District: Shrawasti

Date : 18-10-2023

Depth logged : 165.0 mbgl

Logger use : Robertson

Presence : Rep. of M/S D.S.A.

Construction, Shrawasti

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	To			
1	6	12	6	fine sand	
2	12	28	16	Clay with kankar	
3	28	34	6	fine sand	Good
4	34	46	12	sandy Clay with kankar	
	46	64	18	Clay with kankar	
5	64	69	5	fine sand	Good
6	69	78	9	Clay with kankar	
9	78	84	6	fine sand	Good
10	84	91	7	Clay with kankar	
11	91	96	5	fine sand	Good
12	96	112	16	Clay with kankar	
13	112	118	6	fine sand	Good
14	118	134	16	Clay with kankar	
15	134	144	10	fine sand	Good
16	144	165	21	Clay with kankar	

For First Best Solution

Authorized Signatory

For First Best Solution

Niraj

Proprietor