FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 **Date:22-7-2024**

Geophysical Borehole Logging Report By Dr. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Harabaseri, Block Balha, District Baheraich, U.P.

 ${\bf Name\ of\ Village: } Harabaseri$

Block-Balha

District: Baheraich

Date : 22-7-2024 Drilled Depth: 305 m.bgl Depth logged : 285.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	10	29	19	fine sand
2	29	32	3	Clay
3	32	43	11	fine sand
4	43	47	4	Clay
5	47	58	11	fine sand
6	58	67	9	Sandy Clay
7	67	77	10	fine sand
8	77	81	4	Clay with Kankar
9	81	97	16	fine sand
10	97	101	4	Clay with Kankar
11	101	109	8	fine sand
12	109	116	7	Clay with Kankar
13	116	123	7	fine sand
14	123	125	2	Clay with Kankar
15	125	150	25	fine sand
16	150	157	7	Clay with Kankar
17	157	168	11	fine sand
18	168	191	23	Clay with Kankar
19	191	209	18	fine sand
20	209	212	3	Clay with Kankar
21	212	216	4	fine sand
22	216	243	27	Clay with Kankar

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
23	243	250	7	fine sand
24	250	260	10	Clay with Kankar
25	260	274	14	fine sand
26	274	285	11	Clay with Kankar

For First Best Solution
Authorized Signatory
For First Best Solution
Proprietor