

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:4-5-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Semari Chak Bihani, Block Hariharpur Rani, District Shravasti, U.P.

Name of Village : Semari Chak Bihani (81°56'50.1"E,27°38'02.5"N)

Block – Hariharpur Rani

District: Shravasti

Date : 4-5-2024

Depth logged : 162.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	22	16	fine sand
2	22	37	15	Clay with kankar
3	37	43	6	fine sand
4	43	46	3	Sandy Clay
5	46	48	2	fine sand
6	48	62	14	Clay with kankar
7	62	81	19	fine sand
8	81	86	5	Clay with kankar
9	86	92	6	fine sand
10	92	106	14	Clay with kankar
11	106	152	46	fine sand
12	152	162	10	Sandy Clay

For First Best Solution

Authorized Signatory

For First Best Solution
Niraj
Proprietor