FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005 Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:10-11-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Jeetpur, Block Gesari, District Balrampur, U.P.

Name of Village: Jeetpur

Block - Gesari

District: Balrampur

Date

: 10-11-2023

Depui logge

Depth logged: 263.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S:No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	12	- 6	Sandy Clay
2	12	18	6	Fine sand
4	18	22	4	Clay and kankar
5	22	25	3	Fine sand
6	25	26	1	Clay and kankar
7	26	28	2	Fine sand
8	28	34	6	Clay and kankar
9	34	39	5	Fine sand
10	39	52	13	Clay and kankar
11	52	56	4	Fine sand
12	56	68	12	Clay and kankar
13	68	90	22	Fine sand
14	90	100	10	Clay and kankar
15	100	107	7	Fine sand
16	107	110	3	Clay and kankar
17	110	115	5	Fine sand
18	115	136	21	sandy clay
19	136	145	9	Fine sand
20	145	148	3	Clay and kankar

Mounty

Seem

JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA