IRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER) Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005 Email: - firstbestsolution@yahoo.com Mob: - 8744928231

Date:18-12-2023

GeophysicalBoreholeLoggingReport By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village SemariChakBihani, Block Hariharpur Rani, District Shravasti, U.P.

Name of Village :SemariChakBihani(81°56'50.1"E,27°38'02.5"N)

Block -Hariharpur Rani

District: Shravasti

Date

: 18-12-2023

Logger use

Depth logged: 166.0 mbgl

: Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
5,11	From	То		
1	6	23	17	fine sand
2	23	30	7_	Clay with kankar
3	30	41	11	fine sand
4	41	43	2	Sandy Clay
5	43	48	5	fine sand
6	48	64	16	Clay with kankar
7	64	90	26	fine sand
8	90	107	17	Clay with kankar
9	107	114	7	fine sand
10	114	120	6	Sandy Clay
11	120	144	24	fine sand
12	144	146	2	Sandy Clay
13	146	150	4	fine sand
14	150	160	10	Clay with kankar
	160	164	4	fine sand
15 16	164	166	2	Clay with kankar

For First Best Solution

Authorized Signatory

For First Best Solution

Proprietor

Chamenar Kumar)
FOR V. A. BROTHERS

Auth Signatory