

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date:3-2-2024

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Babhanpurwa, Block Rehara Bazar, District Balrampur, U.P.

Name of Village : Babhanpurwa

Block – Rehara Bazar

District: Balrampur

Date : 3-2-2024

Depth logged : 165.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	35	29	<b>fine sand</b>
2	35	37	2	Sandy clay
3	37	45	8	<b>fine sand</b>
4	45	50	5	Sandy clay
5	50	60	10	<b>fine sand</b>
6	60	73	13	Clay with kankar
7	73	82	9	<b>fine sand</b>
8	82	85	3	Sandy clay
9	85	90	5	<b>fine sand</b>
10	90	112	22	Clay with kankar
11	112	120	8	<b>fine sand</b>
12	120	129	9	Clay with kankar
13	129	134	5	<b>fine sand</b>
14	134	136	2	Sandy clay
15	136	142	6	<b>fine sand</b>
16	142	145	3	Sandy clay
17	145	152	7	<b>fine sand</b>
18	152	165	13	Sandy clay

For First Best Solution

For First Best Solution  
*Niraj*  
Proprietor

