

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date:18-1-2024

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Malda, Block Pachperwa, District Balrampur, U.P.

Name of Village : Malda

Block – Pachperwa

District: Balrampur

Date : 18-1-2024

Depth logged : 232.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	22	16	<b>Fine Sand</b>
2	22	58	36	Clay and kankar
3	58	76	18	<b>Fine sand</b>
4	76	80	4	Clay and kankar
5	80	86	6	<b>Fine sand</b>
6	86	93	7	sandy Clay
7	93	98	5	<b>Fine sand</b>
8	98	114	16	Clay and kankar
9	114	117	3	<b>Fine sand</b>
10	117	122	5	sandy Clay
11	122	129	7	<b>Fine sand</b>
12	129	134	5	Clay and kankar
13	134	138	4	<b>Fine sand</b>
14	138	142	4	Clay and kankar
15	142	163	21	<b>Fine sand</b>
16	163	167	4	Clay and kankar
17	167	172	5	<b>Fine sand</b>
18	172	193	21	Clay and kankar
19	193	212	19	<b>Fine sand</b>
20	212	232	20	sandy Clay

For First Best Solution

Authorized Signatory

For First Best Solution

*Niraj*  
Proprietor