# GEO-PHYSICAL WELL ELECTROLOGGING REPORT

Ref No- 07-01-08/SURYA/2024

Date- 07 Jan 2024

### **DETAILS OF SITE**

VILLAGE -Sugar Nagar BLOCK - Hariaya Satgharwa DISTRICT - Balrampur

Borehole Drilled By-Dara Eco Protection (JV) Balrampur

> Log Report By-Surya Borewell & Traders, Sikandra, Kanpur Dehat



## **SURYA BOREWELL & TRADERS**

Address - Sikandra, Kanpur Dehat

Ref No: - 07-01-07/ SURYA/2024

Date: 07 Jan 2024

## GEOPHYSICAL WELL LOGGING REPORT

#### General Description (As reported)

**Site Location** 

: Vill - Sugar Nagar Block - Hariyaya Satgharwa

District

: Balrampur

**Drilled Depth** 

: 275 m bgl

Borehole drilled by

: Dara Eco Protection (JV) Balrampur.

Logged Depth

: 275 m bgl

**Date of Logging** 

: 07 Jan 2024, 17:45 hrs

Rm & Rsw

: 14.2 Ω-m

& 16.5 Ω-m

Lat. & Long.

: 27.625203 & 82.125514.

Based on interpretation of presented geophysical logs (S.P., Short Normal N16", Long Normal N64" and Lateral 6"), the location of comparatively suitable granular zones is as mentioned below –

S.No	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To The second	发展等。10岁40年6年7年	(as appear)
1	13	21 智慧	题《第四 <b>8</b> 数据》	Good
1.	68	77	9 1	Good
2.		107	24	Good
3.	83	731.74	15	Good
4.	第127章	142	no risherator	Good
5.	152	158	6	Good
6.	168	182	14	
7	210	228	18	Good
7.	238	241	3	Good
8. 9.	253	272	15	Good

Note: -The interpretation of mentioned geophysical logs reveals that-

- 1. Every granular zone contains fine sediments with kanker as per the data given in the table.
- Granular zones other than mentioned above are either highly mixed with clay kanker or very fine,granular zone (127-142), (210-228) & (253-272) are intermixed with thin beds of kankar.
- 3. Quality of formation water up to logging depth is Good.
- 4. Log data Attached.

5

Geophysical Log Interpreted by

Pojeskima

(Rajeev Kumar)

Geophysicist

M. Sc (Tech) Geophysics



# **SURYA BOREWELL & TRADERS**

Address – Sikandra, Kanpur Dehat

