## FIRST BEST SOLUTIONS

## (COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 **Date: 15-10-2023** 

## **Geophysical Borehole Logging Report**

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Dabra, Block Utraula, District Balrampur, U.P.

Name of Village : Dabra (82°23'51.3"E, 27°13'57.8"N)

Block – Utraula District: Balrampur

Date : 15-10-2023 Depth logged : 164.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	36	30	medium to fine sand
2	36	44	8	Clay with kankar
3	44	50	6	Medium sand
4	50	58	8	Clay with kankar
5	58	70	12	fine sand
6	70	75	5	Clay with kankar
7	75	79	4	fine sand
8	79	88	9	Clay with kankar
9	88	102	14	fine sand
10	102	104	2	Clay with kankar
11	104	107	3	fine sand
12	107	118	11	Clay with kankar
13	118	124	6	fine sand
14	124	128	4	Clay with kankar
15	128	136	8	fine sand
16	136	148	12	Clay with kankar
17	148	164	16	fine sand

**For First Best Solution** 

**Authorized Signatory** 

For First Best Solution

roprietor