FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Mob: - 8744928231

Date:31-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Bijuliya, Block Gasari, District Balrampur, U.P.

Name of Village : Bijuliya Block – Gasari

District: Balrampur

Date : 31-10-2023 Depth logged : 275.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	37	31	Fine to medium Sand
2	37	45	8	Clay and kankar
3	45	55	10	Fine sand
4	55	70	15	Clay and kankar
5	70	79	9	Fine sand
6	79	83	4	Clay and kankar
7	83	95	12	Fine sand
8	95	107	12	Clay and kankar
9	107	120	13	Fine sand
10	120	125	5	Clay and kankar
11	125	135	10	Fine sand
12	135	145	10	Clay and kankar
13	145	156	11	Fine sand
14	156	160	4	Clay and kankar
15	160	163	3	Fine sand
16	163	169	6	sandy clay
17	169	175	6	Fine sand
18	175	190	15	Clay and kankar
19	190	195	5	Fine sand
20	195	200	5	Clay and kankar
21	200	227	27	Fine sand

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
22	227	237	10	Clay and kankar
23	237	247	10	Fine sand
24	247	257	10	Clay and kankar
25	257	275	18	Fine sand

For First Best Solution

Authorized Signatory

For First Best Solution

Miraj Proprietor