GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:- 463

Date: - 29-06-2022

NAME OF SITE

Gram Panchayat- Barua

BLOCK- Madnapur

DISTT- Shahjahanpur

NAME OF AGENCY

M/s NCC Ltd. Shahjahanpur



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc_agra@yahoo.com

ISO: 9001: 2015

Ground Water Survey Consultancy

REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- BARUA, BLOCK- MADNAPUR DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 132 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 29.June.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major equifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Defth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 8	3	Clay kankar	
3.	8 - 22	14	Fine to Medium sand	Good
4.	22 - 30	8	Clay kankar	
5,	30 - 87*	57	Medium sand	Good
6.	87 - 98 .	11	Clay kankar	
7.	98 - 114*	16	Medium sand	Good
8.	114 - 130	16	Clay kankar	

Ground Water Survey Consultancy
Agra

Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting starta chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. Expected discharge is 1000 to 1100 L.P.M.
- 5. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 6. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

Topy of Defections

When some first

Defection for the control of 0 Rho:
NI6 (SN,
LAT SES m V Ohm m 당 당 ÷ ÷ ÷ ÷ ģ ģ 40 -56 9 -51 8 \$ Z 5 Same of 5 ß-꾾-ଞӄ-ਨੇ-**\$**-೮-5-8-65 Depth (m) 귱-ಚ-8-**%**-8-3 **%**-**ਭ**-중-ᇙ-=-윰-125 용-[기

