

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:28-4-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Haripur, Block Jhanjhari, District Gonda, U.P.

Name of Village : Haripur

Block – Jhanjhari

District: Gonda

Date : 28-4-2024

Depth logged : 164.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

| S.No | Depth Range (m.bgl) | | Thickness (m) | LITHOLOGY |
|------|------------------------|-----|------------------|-----------------|
| | From | To | | |
| 1 | 6 | 22 | 16 | Fine sand |
| 2 | 22 | 34 | 12 | Sandy clay |
| 3 | 34 | 69 | 35 | Fine sand |
| 4 | 69 | 76 | 7 | Sandy clay |
| 5 | 76 ✓ | 102 | 26 | Fine sand |
| 6 | 102 | 104 | 2 | Clay and kankar |
| 7 | 104 ✓ | 112 | 8 | Fine sand |
| 8 | 112 | 124 | 12 | Clay and kankar |
| 9 | 124 ✓ | 134 | 10 | Fine sand |
| 10 | 134 | 136 | 2 | Sandy clay |
| 11 | 136 ✓ | 140 | 4 | Fine sand |
| 12 | 140 | 142 | 2 | Sandy clay |
| 13 | 142 | 156 | 14 | Fine sand |
| 14 | 156 | 160 | 4 | Clay and kankar |
| 15 | 160 | 164 | 4 | Fine sand |



Jeon
JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA

For First Best Solution

Authorized Signatory

For First Best Solution

Niraj
Proprietor