

# FIRST BEST SOLUTIONS

(Complete Ground Water Service Provider)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date: 10-7-2023

## Geophysical Borehole Logging Report advised by

**Dr. Rajesh Chandra, Sr. Scientist (Retd.),  
Central Ground Water Board**

The geo-electric logging was done in the borehole at village Dhaurara,  
Block Gaindas Bujurg, District Balrampur, U.P.

Name of Village : Dhaurara ( 82°26'59.3", 27°31'44.6')

Block : Gaindas Bujurg

District : Balrampur

Date : 10-7-2023

Depth logged : 166.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	10	34	24	Coarse Sand
2	34	40	6	Cay
3	40	57	17	Fine to medium Sand
4	57	66	9	Clay
5	66	74	8	Fine to medium Sand
6	74	76	2	Clay
7	76	83	7	Fine Sand
8	83	96	13	Clay
9	96	107	11	Medium Sand
10	107	118	11	Clay
11	118	129	11	Medium Sand
12	129	138	9	Clay
13	138	143	5	Fine Sand
14	143	153	10	Clay
15	153	164	11	Medium Sand

For First Best Solution

Authorized  
Signatory

For First Best Solution

*Niraj*

Proprietor