

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date:8-5-2024

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Tendua Nagar, Block Haraya Satgarhwa, District Balrampur, U.P.

Name of Village : Tendua Nagar

Block – Haraya Satgarhwa

District: Balrampur

Date : 8-5-2024

Depth logged : 275.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	20	14	<b>Fine Sand</b>
2	20	23	3	Clay and kankar
3	23	27	4	<b>Fine sand</b>
4	27	52	25	Clay and kankar
5	52	57	5	<b>Fine sand</b>
6	57	66	9	Clay and kankar
7	66	71	5	<b>Fine sand</b>
8	71	78	7	sandy Clay
9	78	82	4	<b>Fine sand</b>
10	82	84	2	Clay and kankar
11	84	87	3	<b>Fine sand</b>
12	87	110	23	Clay and kankar
13	110	115	5	<b>Fine sand</b>
14	115	122	7	Clay and kankar
15	122	133	11	<b>Fine sand</b>
16	133	140	7	Clay and kankar
17	140	148	8	<b>Fine sand</b>
18	148	150	2	Clay and kankar
19	150	155	5	<b>Fine sand</b>
20	155	185	30	Clay and kankar
21	185	197	12	<b>Fine sand</b>
22	197	220	23	Clay and kankar
23	220	234	14	<b>Fine sand</b>
24	234	275	41	Clay and kankar

For First Best Solution  
Authorized Signatory

For First Best Solution  
*Niraj*  
Proprietor