

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:12-2-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Ganvariya Bujurg, Block Utraula, District Balrampur, U.P.

Name of Village : Ganvariya Bujurg (82° 21'45.4" E,27° 14'14.4"N)

Block – Utraula

District: Balrampur

Date : 12-2-2024

Depth logged : 164.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	45	39	fine sand
2	45	48	3	Sandy Clay
3	48	55	7	fine sand
4	55	62	7	Clay with kankar
5	62	71	9	fine sand
6	71	75	4	Sandy Clay
7	75	85	10	fine sand
8	85	90	5	Sandy Clay
9	90	105	15	fine sand
10	105	120	15	Clay with kankar
11	120	125	5	fine sand
12	125	130	5	Clay with kankar
13	130	137	7	fine sand
14	137	149	12	Clay with kankar
15	149	156	7	fine sand
16	156	164	8	Sandy Clay

For First Best Solution

Authorized Signatory

For First Best Solution
Niraj
Proprietor