

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005  
Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)  
Mob: - 8744928231

Date: 8-7-2023

## Geophysical Borehole Logging Report

The geo-electric logging was done in the borehole at village Rajedearwa, Block Pachpedwa, District Balrampur, U.P.

Name of Village: Rajedearwa ( 82°35'31.8", 27°31'44.6')

Block : Pachpedwa

District : Balrampur

Date : 8-7-2023

Depth logged : 240.0 mbgl

Logger use : Robertson

Presence : Rep. of M/S L & T Limited, Gonda

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

Depth (m)		Thickness (m)	zone	Remarks
From	To			
10	18	8	Medium to fine Sand	
18	20	2	Very fine sand	
20	28	8	Medium to fine Sand	
28	33	5	Clay	
33	42	9	Coarse sand	
42	54	12	Very fine sand	
54	64	10	Clay	
64	69	5	Coarse sand	
69	75	6	Clay	
75	80	5	Coarse sand	
80	94	14	fine sand	
94	96	2	Coarse sand	
96	100	4	Clay	

For First Best Solution

*Niraj*  
Proprietor

100	106	6	Medium sand	
106	110	4	Clay	
110	116	6	Coarse sand	
<b>Depth (m)</b>				
<b>From</b>	<b>To</b>	<b>Thickness (m)</b>	<b>zone</b>	<b>Remaks</b>
116	124	8	Clay	
124	142	18	Very fine sand	poor Quality
142	168	26	Fine sand	poor Quality
168	178	10	Medium sand	
178	182	4	Fine sand	
182	185	3	Medium sand	
185	198	13	Very fine sand	poor Quality
198	206	8	Clay	
206	212	6	Very fine Sand	
212	218	4	Medium Sand	
218	220	2	Clay	
220	238	18	Medium Sand	

**For First Best Solution**

Authorized Signatory

**For First Best Solution**

*Niraj*

**Proprietor**