FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER) Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005 Email: -firstbestsolution@yahoo.com Mob: - 8744928231

Date:19-12-2023

 ${\tt Geophysical Borehole Logging Report}$ By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village SekuiyaKasba,

BlockUtraula, District Balrampur, U.P.

Name of Village :SekuiyaKasba(82°24'16" E,27°'18'54"N)

Block –Utraula

District: Balrampur

Date

: 19-12-2023

Depth logged: 164.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered

een decip	merea.			
S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То	•	
1	6	30	24	fine sand
2	30	40	10	Clay with kankar
3	40	70	30	fine sand
4	70	75	5	Clay with kankar
5	75	85	10	fine sand
6	85	93	· 8	Clay with kankar
7	93	95	2	fine sand
8	95	99	4	Clay with kankar
9	99	105	6	fine sand
10	105	110	5	Clay with kankar
11	110	113	3	fine sand
12	113	115	. 2	Clay with kankar
13	115	129	14	fine sand
14	129	140	11	Clay with kankar
15	140	164	24	fine sand

For First Best Solution

Authorized Signatory For First Best Solution Proprietor