IRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER) Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005 Email: - firstbestsolution@vahoo.com Mob: - 8744928231

Date:17-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Utraula Rural, Block

Utraula, District Balrampur, U.P.

Name of Village : Utraula $\bar{R}ural$ (82° 25'20" E,27° '19'32.5"N)

Block – Utraula District: Balrampur

Date

: 17-10-2023

Depth logged: 169.0 mbgl

Logger use : Robertson Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

een deciphered. Thickness (m) LITHOLOGY				
S.No	Depth Range		Thickness (m)	LIMOLOGI
N N 2.11	(m.bgl)			
_	From	To	\$ 10 m	
1	6	24	18	fine sand
2	24	34	10	Clay with kankar
3	34	42	8	fine sand
4	42	46	4	Clay with kankar
5	46	50	4	fine sand
6	50	57	7	Clay with kankar
9	57	78	21	fine sand
10	78	82	4	Clay with kankar
11	82	96	14	fine sand
12	96	126	30	Clay with kankar
		138	12	fine sand
13	126			Clay with kankar
14	138	148	10	
15	148	169	. 21	fine sand

For First Best Solution

Authorized Signatory For First Best Solution