

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:1-2-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Purushottampur, Block Ikauna, District Shrawasti, U.P.

Name of Village : Purushottampur

Block – Ikauna

District: Shrawasti

Date : 1-2-2024

Depth logged : 165.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	35	29	fine sand
2	35	45	10	Clay with kankar
3	45	67	22	fine sand
4	67	85	18	Sandy clay
5	85	97	12	fine sand
6	97	107	10	Clay with kankar
7	107	114	7	fine sand
8	114	120	6	Sandy clay
9	120	144	24	fine sand
10	144	148	4	Sandy clay
11	148	165	17	fine sand

For First Best Solution

Authorized Signatory

For First Best Solution

Niraj
Proprietor