FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 **Date:6-1-2024**

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Mansukha Kanyanpur Block Gilaula, District Shravasti, U.P.

Name of Village: Mansukha Kanyanpur

Block – Gilaula District: Shravasti

Date : 6-1-2024
Depth logged : 162.0 mbgl
Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have

been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	10	4	Sandy Clay
2	10	28	18	fine sand
3	29	33	4	Clay and Kankar
4	33	44	11	fine sand
5	44	50	6	Clay and Kankar
6	50	60	10	fine sand
7	60	65	5	Clay and Kankar
8	65	83	18	fine sand
9	83	87	4	Clay and Kankar
10	87	99	12	fine sand
11	99	110	11	Clay and Kankar
12	110	115	5	fine sand
13	115	118	3	Clay and Kankar
14	118	122	4	fine sand
15	122	128	6	Clay and Kankar
16	128	136	8	fine sand
17	136	138	2	Clay and Kankar
18	138	148	10	fine sand
19	148	150	2	Clay and Kankar
20	150	152	2	fine sand
21	152	162	10	Sandy Clay

For First Best Solution

Authorized Signatory