

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 23-1-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Mohar, Block Colonelganj, District Gonda, U.P.

Name of Village : Mohar

Block – Colonelganj

District: Gonda

Date : 23-1-2024

Depth Drilled: 330 mbgl

Depth logged : 323.0 m.bgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	30	24	Fine Sand
2	30	36	6	Clay and kankar
3	36	43	7	Fine sand
4	43	60	17	Clay and kankar
5	60	75	15	Fine sand
6	75	78	3	sandy Clay
7	78	110	32	Fine sand
8	110	113	3	Clay and kankar
9	113	127	14	Fine sand
10	127	130	3	sandy Clay
11	130	137	7	Fine sand
12	137	167	30	Clay and kankar
13	167	175	8	Fine sand
14	175	195	20	Clay and kankar
15	195	210	15	Fine sand
16	210	215	5	Clay and kankar
17	215	225	10	Fine sand
18	225	240	15	Clay and kankar





JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM (RURAL), GOND

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
19	240	250	10	Fine sand
20	250	256	6	sandy Clay
21	256	264	8	Fine sand
22	264	266	2	sandy Clay
23	266	284	18	Fine sand
24	284	323	39	sandy Clay


 JUNIOR ENGINEER
 DIVISION OFFICE (E/M)
 U.P. JAL NIGAM (RURAL), GONDA

For First Best Solution

Authorized Signatory
 For First Best Solution

 Proprietor

