(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com Mob: - 8744928231

Date: 23-7-2023

## **Geophysical Borehole Logging Report advised** , by Dr. Rajesh Chandra, Sr. Scientist (Retd.),

The geo-electric logging was done in the borehole at village Gouraiya, Block Mihipurwa, District Baharaich, U.P.

Name of Village: Gaurariya and Joganiya Zone - A ( 81° 26'03.5"

E, 28° 02'40.8" N)

Saturnder singh

Block

: Mihipurwa

District

: Baharaich

Date

: 23-7-2023

Depth logged: 300.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	11	22	11	fine sand
2	22	28	6	Clay
3	28	56	28	fine sand
4	56	60	4	Clay
5	60	74	14	fine sand
6	74	82	8	Clay
7	82	96	14	fine sand
7	96	98	2	Clay with Kankar
8	98	101	3	fine sand
9	101	108	7	Clay with Kankar
10	108	114	6	fine sand
11	114	118	4	Clay with Kankar
12	118	132	14	fine sand
13	132	134	2	Clay with Kankar
14	134	147	13	fine sand
15	147	152	5	Clay with Kankar
16	152	156	4	fine sand
17	156	168	12	Clay with Kankar
18	168	206	38	Medium to fine sand

For First Best Solution

Proprietor

19	206	220	14	Clay with Kankar
S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
20	220	240	20	Medium to fine sand
21	240	242	2	Clay with Kankar
22	242	258	16	Medium to fine sand
23	258	260	2	Clay with Kankar
24	260	264	4	Fine sand
`25	264	269	5	Clay with Kankar
26	269	284	15	very fine sand
27	284	300	16	Clay with Kankar

frallh

For First Best Solution

**Authorized Signatory** 

For First Best Solution

Proprietor