FIRST BEST SOLUTION

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005 Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:26-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Gayghat, Block Balha, District Baheraich, U.P.

Name of Village : Gayghat $(27.9739740^{0}N,81.4081780^{0}E)$

Block - Balha

District: Baheraich

: 26-10-2023

Depth logged: 300.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	10	4	Fine Sand
2	10	25	15	Clay and kankar
3	25	43	18	Fine to medium Sand
4	43	55	12	Clay and kankar
5	55	80	25	Fine sand
6	80	83	3	Clay and kankar
7	83	100	17	Fine sand
8	100	107	7	Clay and kankar
9	107	140	33	Fine sand
10	140	155	15	Clay and kankar
11	155	195	40	Fine sand
12	195	220	25	Clay and kankar
13	220	277	57	Fine sand
14	277	280	3	Clay and kankar
15	280	299	19	Fine sand

VIKRAM JEET CONTRACTOR VPO Sirta, Distt.-Kaithal (Haryana)

For First Best Solution

Authorized Signatory