FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 Date: 17-1-2024

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Kuri Todheema Station, Block Colonelganj, District Gonda, U.P.

Name of Village: Kuri Todheema

Block – Colonelganj

District: Gonda

Date

: 17-1-2024

Depth Drilling: 330.0 m.bgl Depth logged: 315.0 m.bgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	27	21	fine sand
2	27	35	8	Clay
3	35	45	10	fine sand
4	45	50	5	Clay
5	50	60	10	fine sand
6	60	63	3	Clay
7	63	90	27	fine sand
8	90	95	5	Clay with Kankar
9	95	105	10	fine sand
10	105	107	2	Clay with Kankar
11	107	115	8	fine sand
12	115	121	6	Clay with Kankar
13	121	124	3	fine sand
14	124	140	16	Clay with Kankar
15	140	145	5	fine sand
16	145	153	8	Clay with Kankar
17	153	165	12	fine sand
18	165	175	10	Clay with Kankar

JUNION THE REPORT OF THE PROPERTY OF THE PROPE



19	175	188	13	fine sand
S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
20	188	197	9	Clay with Kankar
21	197	201	4	fine sand
22	201	205	4	Clay with Kankar
23	205	220	15	fine sand
24	220	223	3	Clay with Kankar
25	223	230	7	fine sand
26	230	245	15	Clay with Kankar
27	245	256	11	Sandy clay
28	256	274	18	fine sand
29	274	281	7	Sandy clay
30	281	286	5	fine sand
31	286	315	29	Clay with Kankar



For First Best Solution

Authorized Signatory For First Best Solution

Miraj Proprietor

