FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com ·

Mob: - 8744928231 Date: 4-3-2024

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Narayanpur, Block Colonelganj, District Gonda, U.P.

Name of Village: Narayanpur

Block: Colonelganj

District: Gonda

Date

: 4-3-2024

Depth Drileed:330 mbgl Depth logged: 330.0 m.bgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	35	29	Fine Sand
2	35	43	8	Clay and kankar
3	43	60	17	Fine sand
4	60	66	6	Clay and kankar
5	66	75	9	Fine sand
6	75	78	3	sandy Clay
7	78	115	37	Fine sand
8	115	135	20	Clay and kankar
9	135	156	21	Fine sand
10	156	174	18	sandy Clay
11	174	184	10	Fine sand
12	184	225	41	sandy Clay
13	225	235	10	Fine sand
14	235	250	15	Clay and kankar
15	250	275	25	Fine sand
16	275	290	15	Clay and kankar
17	290	324	34	sandy Clay
18	324	330	6	Fine sand

For First Best Solution Authorized Signatory

For First Best Solution

Proprietor