

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: -[firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date: 23-11-2023

## Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Tulsipur, Block Belha, District Baheraich, U.P.

Name of Village : Tulsipur (27°55'21.2"N, 81°30'43.2"E)

Block – Belha

District: Baheraich

Date : 23-11-2023

Depth logged : 298.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	25	19	Fine Sand
2	25	30	5	Clay and kankar
3	30	60	30	Fine to medium Sand
4	60	70	10	Clay and kankar
5	70	105	35	Fine sand
6	105	116	11	sandy Clay
7	116	125	9	Fine sand
8	125	130	5	sandy Clay
9	130	155	25	Fine sand
10	155	170	15	Clay and kankar
11	170	180	10	Fine sand
12	180	190	10	sandy Clay
13	190	210	20	Fine sand
14	210	218	8	Clay and kankar
15	218	223	5	Fine sand
16	223	226	3	Clay and kankar
17	226	230	4	Fine sand
18	230	236	6	Clay and kankar
19	236	260	24	Fine sand
20	260	270	10	Clay and kankar
21	270	287	17	Fine sand
22	287	291	4	sandy Clay
23	291	298	7	Fine sand

For First Best Solution

Authorized Signatory  
For First Best Solution

*Niraj*  
Proprietor