

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:3-11-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Gayghat, Block Balha, District Baheraich, U.P.

Name of Village : Gayghat Zone A (28⁰⁰'23.1"N,81⁰⁵'33.7"E)

Block – Balha

District: Baheraich

Date : 3-11-2023

Depth logged : 300.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	20	14	Fine Sand
2	20	26	6	Clay and kankar
3	26	43	17	Fine to medium Sand
4	43	60	17	Clay and kankar
5	60	103	43	Fine sand
6	103	112	9	Clay and kankar
7	112	150	38	Fine sand
8	150	155	5	Clay and kankar
9	155	160	5	Fine sand
10	160	167	7	Clay and kankar
11	167	205	38	Fine sand
12	205	210	5	Clay and kankar
13	210	224	14	Fine sand
14	224	230	6	Clay and kankar
15	230	240	10	Fine sand
16	240	246	6	Clay and kankar
17	246	259	13	Fine sand
18	259	264	5	Clay and kankar
19	264	277	13	Fine sand
20	277	281	4	sandy clay

Satvinder Singh Govt. Contractor

Satvinder Singh

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
21	281	289	8	Fine sand
22	289	291	2	sandy clay
23	291	300	9	Fine sand

Satvinder Singh Govt. Contractor

Satvinder Singh

For First Best Solution

Authorized Signatory
For First Best Solution

Niraj
Proprietor