

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:15-9-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Haljot Gajobari, Block Harihar Pur, District Shravasti, U.P.

Name of Village : Haljot Gajobari (82.40°E,27.04° N)

Block – Harihar Pur

District: Shravasti

Date : 15-9-2023

Depth logged : 166.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	16	10	Medium sand
2	16	24	8	Clay with kankar
3	24	36	12	Medium sand
4	36	56	20	Clay with kankar
5	56	64	8	fine sand
6	54	66	12	Clay with kankar
7	66	74	8	fine sand
8	74	96	22	Clay with kankar
9	96	107	11	fine sand
10	107	114	7	Clay with kankar
11	114	145	31	medium to fine sand
12	145	156	11	Clay with kankar
13	156	166	10	fine sand

For First Best Solution

Authorized Signatory

For First Best Solution

Niraj

Proprietor