

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date: 7-3-2024

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Narayana pur Zone 1 Block Gilaula, District Shravasti, U.P.

Name of Village :

Narayanapur zone 1

Block – Gilaula

District: Shravasti

Date : 7-3-2024

Depth logged : 165.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	40	34	<b>Fine Sand</b>
2	40	55	15	Clay and kankar
3	55	62	7	<b>Fine sand</b>
4	62	65	3	Clay and kankar
5	65	70	5	<b>Fine sand</b>
6	70	75	5	Clay and kankar
7	75	90	15	<b>Fine sand</b>
8	90	95	5	Clay and kankar
9	95	106	11	<b>Fine sand</b>
10	106	113	7	Clay and kankar
11	113	120	7	<b>Fine sand</b>
12	120	123	3	sandy Clay
13	123	142	19	<b>Fine sand</b>
14	142	165	23	sandy Clay

For First Best Solution

Authorized Signatory  
For First Best Solution

*Niraj*  
Proprietor