

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:23-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Chandanpur, Block Belha, District Baheraich, U.P.

Name of Village : Chandanpur ($27^{\circ}55'00.2''N, 81^{\circ}23'20.6''E$)

Block – Belha

District: Baheraich

Date : 23-10-2023

Depth logged : 300.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	20	14	Fine Sand
2	20	25	5	Clay and kankar
3	25	95	70	Fine to medium Sand
4	95	103	8	Clay and kankar
5	103	110	7	Fine sand
6	110	145	35	Clay and kankar
7	145	204	59	Fine sand
8	204	211	7	Clay and kankar
9	211	220	9	Fine sand
10	220	250	30	sandy Clay
11	250	265	15	Fine sand
12	265	275	10	sandy Clay
13	275	290	15	Fine sand
14	290	300	10	Clay and kankar

Vikram Jeet

For First Best Solution

Authorized Signatory
For First Best Solution

Niraj
Proprietor