

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:11-1-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Bakwa-II, Block Sirsiya, District Shrawasti, U.P.

Name of Village : Bakwa-II (82°01'41.38"E, 27°42'01.0"N)

Block – Sirsiya

District: Shrawasti

Date : 11-1-2024

Depth logged : 165.0 m.bgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	24	18	fine sand
2	24	39	15	Clay with kankar
3	39	43	4	fine sand
4	43	45	2	Clay with kankar
5	45	54	9	fine sand
6	54	65	11	Clay with kankar
7	65	70	5	fine sand
8	70	74	4	Clay with kankar
9	74	86	12	fine sand
10	86	110	24	Clay with kankar
11	110	133	23	fine sand
12	133	137	4	Clay with kankar
13	137	145	8	fine sand
14	145	147	2	Sandy clay
15	147	157	10	fine sand
16	157	165	8	Sandy clay

For First Best Solution
Authorized Signatory

For First Best Solution

Proprietor