

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:3-12-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Gajobari, Block Jamunha, District Shravasti, U.P.

Name of Village : Gajobari (81°48'21.4"E, 27°51'36.9"N)

Block – Jamunha

District: Shravasti

Date : 3-12-2023

Depth logged : 162.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	To			
1	5	8	3	Sandy clay	
2	8	10	2	fine to medium sand	Good
3	10	18	8	Clay with kankar	
4	18	24	6	fine sand	Good
5	24	28	4	Clay with kankar	
6	28	36	8	fine sand	Good
7	36	60	24	Clay with kankar	
8	60	62	2	fine sand	Good
9	62	80	18	Sandy clay	
10	80	88	8	fine sand	Good
11	88	96	8	Sandy clay	
12	96	102	6	fine sand	Good
13	102	106	4	Clay with kankar	
14	106	114	8	fine sand	Good
15	114	118	4	Clay with kankar	
16	118	122	4	fine sand	Good
17	122	127	5	Clay with kankar	
18	127	139	12	fine sand	Good
19	139	148	9	Clay with kankar	
20	148	154	6	fine sand	Good
21	154	162	8	Clay with kankar	

For First Best Solution

For BEST PUMPS SALE & SERVICE
Vino

Proprietor

Authorized Signatory
For First Best Solution

Niraj
Proprietor

POINCE
JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA