FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 Date:26-12-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Manki, Block Gasari, District Balrampur, U.P.

Name of Village : Manki

Block – Gasari District: Balrampur Date : 26-12-2023 Depth logged : 274.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	30	24	fine sand
2	30	43	13	Clay with kankar
3	43	53	10	fine sand
4	53	64	11	Clay with kankar
5	64	74	10	fine sand
6	74	85	11	Clay with kankar
7	85	95	10	fine sand
8	95	105	10	Clay with kankar
9	105	111	6	fine sand
10	111	116	5	Clay with kankar
11	116	120	4	fine sand
12	120	125	5	Clay with kankar
13	125	136	11	fine sand
14	136	145	9	Clay with kankar
15	145	176	31	fine sand
16	176	180	4	Clay with kankar
17	180	190	10	fine sand
18	190	203	13	Clay with kankar
19	203	235	32	fine sand
20	235	245	10	Clay with kankar
21	245	250	5	fine sand
22	250	255	5	Clay with kankar
23	255	266	11	fine sand

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
24	266	268	2	Clay with kankar
25	268	274	6	fine sand

For First Best Solution

For First Best Solution Authorized Signatory Proprietor