

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date: 4-1-2024

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Majhauwa, Block Gesari, District Balrampur, U.P.

Name of Village : Majhauwa

Block – Gesari

District: Balrampur

Date : 4-1-2024

Depth logged : 274.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	12	6	<b>fine sand</b>
2	12	28	16	Clay with kankar
3	28	56	28	<b>fine sand</b>
4	56	67	11	Clay with kankar
5	67	97	30	<b>fine sand</b>
6	97	100	3	Clay with kankar
7	100	105	5	<b>fine sand</b>
8	105	117	12	Clay with kankar
9	117	130	13	<b>fine sand</b>
10	130	146	16	Clay with kankar
11	146	160	14	<b>fine sand</b>
12	160	175	15	Clay with kankar
13	175	183	8	<b>fine sand</b>
14	183	188	5	Clay with kankar
15	188	196	8	<b>fine sand</b>
16	196	202	6	Clay with kankar
17	202	209	7	<b>fine sand</b>
18	209	225	16	Clay with kankar
19	225	243	18	<b>fine sand</b>
20	243	257	14	Clay with kankar
21	257	274	17	<b>fine sand</b>

For First Best Solution

For First Best Solution  
Authorized Signatory

*Niraj*  
Proprietor