

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:15-12-2023

## Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Bhikhpur Tarai Beni Dihua, Block Sirsiya, District Shrawasti, U.P.

Name of Village : Bhikhpur Tarai Beni Dihua (82°01'22.3"E, 27°36'37.5"N)

Block – Sirsiya

District: Shrawasti

Date : 15-12-2023

Depth logged : 165.0 m.bgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	23	17	fine sand
2	23	29	6	Clay with kankar
3	29	35	6	fine sand
4	35	38	3	Clay with kankar
5	38	49	11	fine sand
6	49	64	15	Clay with kankar
7	64	80	16	fine sand
8	80	92	12	Clay with kankar
9	92	130	38	fine sand
10	130	132	2	Clay with kankar
11	132	140	8	fine sand
12	140	146	6	Clay with kankar
13	146	150	4	fine sand
14	150	165	15	Clay with kankar

For First Best Solution  
Authorized Signatory

For First Best Solution  
*Niraj*  
Proprietor

For BEST PUMPS SALE & SERVICE  
*Vinay*  
Proprietor

*Deen*  
*Deen*

ASSISTANT ENGINEER  
DIVISION OF  
U.P. JAL N...