

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: -firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 28-7-2023

Geophysical Borehole Logging Report

By **Sh. R. Chandra, Sr. Scientist (Retd.)**

The geo-electric logging was done in the borehole at village God Purwa, Block HariharpurRani, District Shravasti, U.P.

Name of Village : God Purwa, (81.94°E, 27.665°N)

Block -- HariharpurRani

District: Shravasti

Date : 28-7-2023

Depth logged : 167.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	10	18	8	medium to fine sand
2	18	30	12	Clay with kankar
3	30	37	7	medium sand
4	37	45	8	Clay with kankar
5	45	50	5	fine sand
6	50	54	4	Clay with kankar
7	54	58	4	fine sand
8	58	62	4	Clay with kankar
9	62	80	18	medium to fine sand
10	80	90	10	Clay with kankar
11	90	102	12	fine sand
12	102	108	6	Clay with kankar
13	108	113	5	fine sand
14	113	117	4	Clay with kankar
15	117	130	13	fine sand
16	130	134	4	Clay with kankar
17	134	143	9	fine sand
18	143	148	5	Clay with kankar
19	148	152	4	fine sand
20	152	167	15	Clay with kankar

For First Best Solution

Authorized Signatory

For First Best Solution

Alvarg
Proprietor

Alvarg