FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 Date:19-10-2023

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Trilokpur, Block Hariharpur Rani, District Shrawasti, U.P.

Name of Village : Trilokpur Block – Hariharpur Rani District: Shrawasti Date : 19-10-2023 Depth logged : 164.0 mbgl Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY	Quality
	From	То			
1	6	22	16	fine sand	Good
2	22	26	4	Clay with kankar	
3	26	38	12	fine sand	Good
4	38	46	8	Clay with kankar	
5	46	54	8	fine sand	Good
6	54	62	8	Clay with kankar	
9	62	80	18	fine sand	Good
10	80	85	5	Clay with kankar	
11	85	98	13	fine sand	Good
12	98	110	12	Clay with kankar	
13	110	129	19	fine sand	Good
14	129	134	5	Clay with kankar	
15	134	146	12	fine sand	Good
16	146	156	10	Clay with kankar	
17	156	164	8	fine sand	Good

For First Best Solution For First Best Solution Miraj Proprietor Authorized Signatory