

# FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - [firstbestsolution@yahoo.com](mailto:firstbestsolution@yahoo.com)

Mob: - 8744928231

Date: 26-4-2024

## Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Narayana Zone 2 Block Gilaula, District Shravasti, U.P.

Name of Village : Narayana Zone 2

Block – Gilaula

District: Shravasti

Date : 26-4-2024

Depth logged : 110.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	20	14	<b>Fine sand</b>
2	20	30	10	Clay and kankar
3	30	38	8	<b>Fine sand</b>
4	38	41	3	Clay and kankar
5	41	50	9	<b>Fine sand</b>
6	50	55	5	Clay and kankar
7	55	65	10	<b>Fine sand</b>
8	65	70	5	Clay and kankar
9	70	82	12	<b>Fine sand</b>
10	82	85	3	Sandy clay
11	85	101	16	<b>Fine sand</b>
12	101	110	9	Clay and kankar

For First Best Solution

Authorized Signatory

For First Best Solution

*Niraj*  
Proprietor