IRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: -firstbestsolution@yahoo.com

Mob: - 8744928231

Date:20-9-2023

GeophysicalBoreholeLoggingReport By Sh. R. Chandra, Sr. Scientist (Retd.)

geo-electric logging was done in the bore hole at village Banktwa Mohali, Block Jamunaha, District Shravasti, U.P.

NameofVillage:Banktwa Mohali (81.637296°E,27.830916°N)

Block-Bankatwa District: Shrayasti

:20-9-2023

Depthlogged :164.0mbgl

Loggeruse

:Robertson

Based on the Interpretation report from geophysical Logchart following granular zones have been deciphered.

| S.No | Depth Range (m.bgl) | | Thickness (m) | LITHOLOGY |
|------|------------------------|-----|---------------|---------------------|
| | From | То | | |
| 1 | 6 | 32 | 26 | fine to medium sand |
| 2 | 32 | 40 | 8 | clay with Kankar |
| 3 | 40 | 52 | 12 | fine to medium sand |
| 4 | 52 | 70 | 18 | clay with Kankar |
| 5 | 70 | 110 | 40 | fine to medium sand |
| 6 | 110 | 126 | 16 | clay with Kankar |
| 7 | 126 | 158 | 32 | fine to medium sand |
| 8 | 158 | 164 | 8 | clay with Kankar |

For First Best Solution

Authorized Signatory

For First Best Solution