

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:13-10-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Hasanpur, Block Haraya Satgharwa, District Balrampur, U.P.

Name of Village : Hasanpur (82° 13'46" E, 27° 43'08.1"N)

Block – Haraya Satgharwa i

District: Balrampur

Date : 13-10-2023

Depth logged : 284.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	12	6	fine sand
2	12	65	53	Clay with kankar
3	65	77	12	fine sand
4	77	84	7	Clay with kankar
5	84	88	4	fine sand
6	88	104	16	Clay with kankar
9	104	114	10	fine sand
10	114	124	10	Clay with kankar
11	124	132	8	fine sand
12	132	146	14	Clay with kankar
13	146	151	5	fine sand
14	151	158	7	Clay with kankar
15	158	166	8	fine sand
16	166	188	22	Clay with kankar
17	188	192	4	fine sand
18	192	215	23	Clay with kankar
19	215	220	5	fine sand
20	220	242	22	Clay with kankar
21	242	246	4	fine sand
22	246	255	9	Clay with kankar
23	255	266	11	fine sand
24	266	274	8	Clay with kankar
25	274	282	8	fine sand

Chandra

Seen

SR

JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA