

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date:3-10-2023

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Itai, Block Gasari, District Balrampur, U.P.

Name of Village : Itai (82° 29'03.2" E, 27° 22'15.6"N)

Block – Gasari

District: Balrampur

Date : 3-10-2023

Depth logged : 275.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	20	14	Medium to fine sand
2	20	28	8	Clay with kankar
3	28	41	13	Medium to fine sand
4	41	70	29	Clay with kankar
5	70	92	22	fine sand
6	92	106	14	Clay with kankar
9	106	124	18	fine sand
10	124	145	21	Clay with kankar
11	145	161	16	fine sand
12	161	190	29	Clay with kankar
13	190	203	13	fine sand
14	203	238	35	Clay with kankar
15	238	252	14	fine sand
16	252	260	8	Clay with kankar
17	260	274	14	fine sand

For First Best Solution

Authorized Signatory

For First Best Solution

Niraj

Proprietor