

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 20-1-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Birpur Bhojpur, Block Gesari, District Balrampur, U.P.

Name of Village : Birpur Bhojpur

Block – Gesari

District: Balrampur

Date : 20-1-2024

Depth logged : 274.0 mbgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	12	6	fine sand
2	12	20	8	Clay
3	20	30	10	fine sand
4	30	45	15	Clay
5	45	48	3	fine sand
6	48	52	4	Clay
7	52	60	8	fine sand
8	60	84	24	Clay with Kankar
9	84	80	-4	fine sand
10	80	100	20	Clay with Kankar
11	100	110	10	fine sand
12	110	125	15	Clay with Kankar
13	125	134	9	fine sand
14	134	145	11	Clay with Kankar
15	145	152	7	fine sand
16	152	166	14	Clay with Kankar
17	166	172	6	fine sand
18	172	185	13	Clay with Kankar
19	185	190	5	fine sand
20	190	196	6	Clay with Kankar
21	196	205	9	fine sand

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
22	205	210	5	Clay with Kankar
23	210	220	10	fine sand
24	220	230	10	Clay with Kankar
25	230	242	12	fine sand
26	242	255	13	Clay with Kankar
27	255	265	10	fine sand
28	265	274	9	Sandy clay

Authorized Signatory

For First Best Solution

For First Best Solution

Proprietor