

FIRST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231

Date: 2-5-2024

Geophysical Borehole Logging Report

By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Saraiya, Block Colonelganj, District Gonda, U.P.

Name of Village : Saraiya

Block – Colonelganj

District: Gonda


Date : 2-5-2024

Depth logged : 330.0 m.bgl

Logger use : Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
1	6	35	29	Fine Sand
2	35	42	7	Clay and kankar
3	42	48	6	Fine sand
4	48	52	4	Clay and kankar
5	52	66	14	Fine sand
6	66	71	5	Clay and kankar
7	71	116	45	Fine sand
8	116	130	14	sandy Clay
9	130	147	17	Fine sand
10	147	176	29	Clay and kankar
11	176	187	11	Fine sand
12	187	219	32	Clay and kankar
13	219	235	16	Fine sand
14	235	255	20	Clay and kankar
15	255	275	20	Fine sand
16	275	277	2	sandy Clay
17	277	283	6	Fine sand
18	283	296	13	Clay and kankar
19	296	303	7	Fine sand

SR

JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA



S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	To		
20	303	315	12	Clay and kankar
21	315	324	9	Fine sand
22	324	330	6	sandy Clay

gaur

JUNIOR ENGINEER
DIVISION OFFICE (E/M)
U.P. JAL NIGAM RURAL GONDA

For First Best Solution

Authorized Signatory

For First Best Solution

Niraj
Proprietor

